

Roadway Condition Photos

Project: South Ripley Solar – Route Evaluation Study

Our reference: Your reference: Case No.

Prepared by: J. Sowinski Date: 8/12/2020


Approved by: Checked by:

Subject: Appendix 16 - Roadway Condition Photos

This document is issued for the party which commissioned it and for specific purposes connected with the above-captioned project only. It should not be relied upon by any other party or used for any other purpose.

We accept no responsibility for the consequences of this document being relied upon by any other party, or being used for any other purpose, or containing any error or omission which is due to an error or omission in data supplied to us by other parties.

This document contains confidential information and proprietary intellectual property. It should not be shown to other parties without consent from us and from the party which commissioned it.







07 - West Main Street (Rt 20) looking west

08 - West Main Street (Rt 20) looking east





09 - West Main Street (Rt 20) looking west

10 - West Main Street (Rt 20) looking east





11 - West Main Street (Rt 20) looking west

12 - West Main Street (Rt 20) looking east

